

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

JO1369  
West  
> 1  
1.725 mi.  
9109 ft.

4823 BEACH 48TH ST  
4823 BEACH 48TH ST  
BROOKLYN, NY  
Site 3 of 3 in cluster JO

NY Spills S104650604  
N/A

Relative:  
Higher  
Actual:  
0 ft.

SPILLS:

Name: 4823 BEACH 48TH ST  
Address: 4823 BEACH 48TH ST  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0000776 / Not Reported  
Facility ID: 0000776  
Facility Type: ER  
DER Facility ID: 224392  
Site ID: 276005  
DEC Region: 2  
Spill Cause: Unknown  
Spill Class: B3  
SWIS: 2401  
Spill Date: 2000-04-06  
Investigator: EJKIM  
Referred To: Not reported  
Reported to Dept: 2000-04-19  
CID: 312  
Water Affected: Not reported  
Spill Source: Institutional, Educational, Gov., Other  
Spill Notifier: Other  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 1  
Date Entered In Computer: 2000-04-19  
Spill Record Last Update: 2019-08-26  
Spiller Name: Not reported  
Spiller Company: RABBI ELGARTEN  
Spiller Address: Not reported  
Spiller Company: 001  
Contact Name: Not reported  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was  
TIPPLE 01/22/2002 AFTER PRELIMINARY REVIEW OF THE 1/14/02 SUBMISSION  
WHERE AKRF, INC. REFUSED TO DO A WATER SAMPLE ANALYSIS. DUE TO  
PROXIMITY OF THE LEAKING TANK TO GROUNDWATER, DEC HAS DETERMINED THAT  
THE SUBMISSION WILL BE REVEIUED WHEN A WATER SAMPLE ANALYSIS IS  
SUBMITTED. 4/10/03 NO GROUNDWATER SAMLPE SUBMITTED TO DATE. June 2005  
- Spill lead to Maloney as part of the Spill Initiative August 15,  
2005 - Spoke with Rabbi Elgarten. He said the spill was minor and  
cleaned up. I requested a report detailing such from his consultant.  
He said he will contact his consultant. ~Maloney August 18, 2005 -  
Spoke with consultant. The consultant forwarded report. No record of  
groundwater sample was included. -Maloney Follow-up needs to be done  
with consultant re: gw sampling. - Maloney 4/1/09 - Austin -  
Transferred from Needs Reassignment to Zhune for further work to  
remediate and close - end 8/26/19 - Spill reassigned to Kim as per  
Obligado."  
Remarks: "SOIL SAMPLE RESULTS CAME BACK POSITIVE FOR CONTAMINATION"  
All Materials:  
Site ID: 276005

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Operable Unit ID: 822539  
Operable Unit: 01  
Material ID: 289014  
Material Code: 0001A  
Material Name: #2 fuel oil  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: .00  
Units: G  
Recovered: .00  
Oxygenate: Not reported